



INTEGRITY

ENVIRONMENTAL SERVICES, INC.

1240 IROQUOIS DRIVE
SUITE 102
NAPERVILLE, IL 60563

630-718-9133
FAX 630-718-9114

August 21, 2018

C-12539

Mr. Mike Duggan
Facilities Director
Community Consolidated School District 181
115 West 55th Street
Clarendon Hills, Illinois 60514

Dear Mike:

Roofing Repair Inspection and Observation Summary
Roof Repair Work
Elm Elementary School
15W201 60th Street
Burr Ridge, Illinois
IES No. 915-36


Between July 16, 2018 and August 16, 2018, a representative of Integrity Environmental Services, Inc. (IES) performed periodic inspections of the partial roof tear-off and repair work at the above referenced Community Consolidated School District 181 school building. The project also includes the replacement of new roofing materials, which is scheduled for completion in August 2018. R.B. Crowther Roofing was retained by the School District to perform the work needed to complete this roofing replacement work.

The removal work included cutting and removing layers of the roofing materials to the roof deck (metal or concrete) at specific areas of Elm School only. Cleaning and disposing of all debris from roof surfaces was also performed prior to the installation of new roofing materials. At no time did the IES representative observe moisture or areas exhibiting mold or mold growth during the periodic inspections.

We have enclosed for reference, a copy of a hand-sketched plan drawing illustrating the roof repair areas/locations.

As always, if there are any questions or comments, please feel free to contact the undersigned at (630) 718-9133.

INTEGRITY ENVIRONMENTAL SERVICES, INC.




Mark J. Ravanese
President

Enclosure

cc: Ms. Debbie Prasch (e-mail only)
Mr. Dave Patton (e-mail only)

ELW School Roof work - 2013



2 ↑