



August 1, 2019

C-12818

Mr. Mike Duggan
Director of Facilities
Community Consolidated School District 181
115 West 55th Street
Clarendon Hills, Illinois 60514

Dear Mike:

Summary of Analytical Findings
July 2019 Potable Water Source Lead Sampling
Community Consolidated School District 181
Walker Elementary School
120 Walker Avenue
Clarendon Hills, Illinois
IES Project No. 915-43

This report has been prepared to summarize the analytical findings of the additional water testing performed at all potable water sources within Walker Elementary School. This additional water testing was requested due to a summer construction project that included the replacement of the water main at Walker Avenue that connects the school to the municipal water source.

On July 10, 2019, a representative of Integrity Environmental Services, Inc. (IES) was present at the school to collect first draw and flush second draw water samples identical to sampling protocol of the State's lead-in-water testing program (Public Act 099-0922) and the 2018 requirements. The IES representative collect a total of seventy-three (73) samples from thirty-six (36) water sources. It should be noted that three (3) water samples were obtained from the recently installed bottle-filler/water cooler combination unit, as required by sampling protocol.

As can be seen on the attached water sample data spreadsheet, none of the samples were above the regulatory safe level threshold of 5.0 parts per billion (ppb). In fact, many sample locations reported "non-detect" (ND) results, while all remaining water samples resulted in levels below 1.0 ppb. These analytical results are in compliance with the current Illinois Department of Public Health (IDPH) regulations concerning lead in potable water.

As always, if you have any questions, please feel free to contact the undersigned at (630) 718-9133.

INTEGRITY ENVIRONMENTAL SERVICES, INC.

Mark J. Ravanesi

Attachment